

ATA Code	EASA Rating	Gerätegruppe	Herstellergruppe Baureihen/Serie Mustergruppe	Einzelmuster Partnummern	Instandhaltungsumfang	Genehmigte Instandhaltungs- Unterlage *
24/33	C5 Electrical Power & Lights	Batteries	Concorde	RG-380E/40L, RG-380E/60L, RG-443	Shop Maintenance Overhaul	CMM online
			Gill	G-6381E		CMM online
			Hawker/ Varta	33490409209		CMM online
			Honeywell/ Grimes	60-3844-1, 60-3844-3, 61-0478-9, 61-3800-1		CMM online
			L3/ Jet	501-1075-01, 501-1075-02, 501-1228-03, 501-1228-04, 501-1712-01, 501-1318-01, 501-1712-02		CMM online
			Marathon	30978-002, 31879-001, 32043-001, 32441-002, 32472-001, 39161-001		CMM online
			Diehl	3240-30, 3240-31, 3301-31		CMM online
			Saft	1756-1, 1756-3, 2778-1, 2778-14, 442CH1, 4078-3, 4078-4, 40178-24, 40178-26, 40678-2, 40678-4, 401176-9 5912855-01 427CK-1, 024055-000 257CH-9, 024054-000		CMM online
		UTC	8ES360000-50	CMM online		
Lights	Diehl	3253-10 3367-10, 3367-11	Shop Maintenance Repair	CMM online		
32	C14 Landing Gear	Wheels	Meggitt/ABSC	90002024 (2610701-2), 90002024-1	Shop Maintenance Overhaul with NDT	CMM AP-857 online
			Meggitt/ABSC	90002021 (2610485-1) 90002021-1		CMM AP-859 online
			Meggitt/ABSC	AHA2225		CMM AP-2152 online
			Meggitt/ABSC	AHA 2226		CMM AP-2153 online
			Meggitt/ABSC	9544207		CMM AP-494 online
			Meggitt/ABSC	5011740		CMM AP-742 online

ATS GmbH
DE.145.0479

Befähigungsliste
(Capability List) Sehlem



ATA Code	EASA Rating	Gerätegruppe	Herstellergruppe Baureihen/Serie Mustergruppe	Einzelmuster Partnummern	Instandhaltungsumfang	Genehmigte Instandhaltungs-Unterlage*
52	C4 Türen und Luken	Passenger door	DO 328 Support Services GmbH	001A521A0016200	FVK Reparatur	TM-SRM -300493-ALL
25	C6 Ausrüstung	Flight Comp/cover window frame	DO 328 Support Services GmbH	001A251A2121002	FVK Reparatur	TM-CRM -051-001-ALL
		Engine Cowling	DO 328 Support Services GmbH	001B711E2101000		TM-CRM -051-001-ALL
27 /55/57	C8 Flight controls	Spoilers	DO 328 Support services	001B577A1200002	FVK Reparatur	TM-SRM -300493-ALL
		Leading Edge	DO 328 Support Services GmbH	001B574A2000005 / 001A574A3000001	Boot replacement	TM-SRM -300493-ALL
56	C19 Fenster	Passenger Comp./window	Sully	001A562A0015000	FVK Reparatur	CMM Sully 56-21-84
53	C20 Struktur	Floor panel	DO 328 Support Services GmbH	001A539A5490000	FVK Reparatur	TM-SRM -300493-ALL

QM-Bestätigung QM-verification			Antragstellende Person Person who requests amending			LBA Genehmigung LBA approval			
Tanja Bleimehl	02.02.2023		Nico Lange (AccM)	02.02.2023		Angebr.	AFT 705	23.06.23	
Name	Date (dd,mm,yy)	Signature	Name	Date (dd,mm,yy)	Signature	Name	Date (dd,mm,yy)	Signature	

*nach aktuell gültiger Rev.